







Some of the vegetation appears to have been in piles for a long

time.



Almost everything has been removed from the site



There are junked cars on the edge of the property



There are areas of minor soil staining



There are residential properties on the east boundary



Junked vehicles on the edge of the property



There are piles of rubble on the edge of the property which may have originated on the property.



There is galvanize metal in some of the piles.



Looking towards Queen Louise Home



There were cars on the site.



The debris in the piles includes engine parts



The site is clean

JANUARY 2022



Guinea grass has overgrown most of the site



There are no areas of stressed vegetation



There is some herbaceous vegetation



The surrounding properties has not changed.



The parcel is no finished.



There is still some debris visible through the grass.



The areas beyond the fence are more heavily





There is a large amount of debris to the south.