

Existing Site Photographs



Figure 1: Aerial View of Site

Existing Site Photographs



Figure 2: Hurricane Damaged Maintenance Building



Figure 3: Hurricane Damaged Maintenance Building

Existing Site Photographs



Figure 4: Hurricane Damaged Maintenance Building



Figure 5: Hurricane Damaged Maintenance Building

Existing Site Photographs



Figure 6: Hurricane Damaged Maintenance Building

Existing Site Photographs



Figure 7: Hurricane Damaged Maintenance Building

Existing Site Photographs



Figure 8: Hurricane Damaged Maintenance Building

PARCEL NO. 6 ESTATE SUSANNABERG

Existing Site Photographs



Figure 9: Hurricane Damaged Maintenance Building



Figure 10: Hurricane Damaged Maintenance Building

Existing Site Photographs



Figure 11: View along Public Road

Existing Site Photographs



Figure 12: View From Public Road



Figure 13: DPW / VITEMA Office Building